

2006

4760

combine

pg 2

~~10-5-15~~ 2554 1879 change oil JD15w40t50
 10-23-17 2860 2092 change oil JD15w40t50 Filter inner air AH 212295
 outer air ~~AH 173940~~ engine Filter RE509672
~~fuel filter AH 128449~~ fuel ~~filter~~

8-2-18 2981 2175

New fuel filters RE525523 kit

11-5-18 3055

change 3 hyd filters AH 128449

7-6-19 9123 2296

drain & put in new Anti-Freeze JD coolant

11-11-19 3251 2390

change oil JD15w40t50

8-28-2020 3273 2405

New inner air AH 212295 & outer air AH 212294

7-3-2021 3408 2503

(3 Hydro Filters) (New Fuel Filters)
AH 128449 (New RE 525523)

~~7-3-2021~~ 3382 2484

change feeder-hous reverser oil #TY26408
change Primary counter shaft gear-case JD 80.90

change straw chopper rotor knives & bottom sheet metal plate

New Gasket on engine by fan end towards back side of engine

New (4) Tires on combine & front (R) Feeder house

Lift cylinder rebuild

change a lot of things so on another paper

change oil JD15w40

engine separator 3700-2707 hrs

9-16-2022 3805 2784 New fuel filters RE525523 kit & 1 new fuel line

10-12-2022 3830 2804 Jan worked on combine (separate sheet attached)

replaced unlead tension cylinder AH 176248 - hyd hose

union on separator drive pulley AH 218290 - replace hyd

couplers on Quick Coupler for head did both fronts AXE 80983
Back Feeder house floor AH 173940 - New chopper knives 35-
H 215004 - replace Exhaust Manifold Gasket

Pete

6-2-2020 733914 change oil JD15w40 +50

9-4-2020 738122 change air dryer filter Ac1001 + new filter in power steering Tank NAPA 7557

~~6-12-2021~~ 745922 New Flasher # FP37 - + New Turn Signal

~~10-5-2021~~ switch # TL10750 New all 6 injectors \$5300.00 + both fuel filters

12-10-2021 754148 New Seal in Back axle Left side Seal # SKF 47697

12-20-2021 754180 change oil JD15w40 +50 + NAPA filter 1792XE

1-22-2022 756733 change front fuel NAPA.3674 + back fuel NAPA.3405

3-8-22 758944 New air hoses between tractor + trailer Red 81-0015-40R Blue 81-0015-40B Baldwin PA2608 from Graybills

3-22-2022 760205 New air filters Baldwin PA2608 from Graybills

6-28-2022 763332 New Horizon air fan clutch assembly

9-30-2022 766706 put on Peccar 144561 + Temp sw 215ND Right front engine Temperature sender, \$325.00

10-27-2022 769039 New Batterys from Mac's \$325.00

12-9-2022 769233 New Brakes front drive Axle (Wisdom W/ 4311E-23KW also New Brake drums + put on 8 Rear tires New

12-17-2022 769632 New air dryer filter MFGSA 323 from Graybills 39.66

2-14-2023 771727 Front Fuel filter 3674 Back fuel 3405

2-23-23 New air tank ~~inside~~ Behind Battery Box (mp GS 29592 also Coolant level sensor S291203 \$28.40 39758) Did NOT fix engine check light still on.

2-2-2023 772206 change oil JD15w40 +50 + Baldwin filter 899 also New Governor on air compressor Bendix OR275491X

4-11-2023 774416 change oil Transmission put in switches 50w5 from Koch's

5-1-2023 774500 New Temperature sensor front end Block part # 102-2240 cat made

2517 1-23-2021 Change oil JD 15w40 #50
2912 5-11-2021 Change oil JD 15w40 50R Filter RE504836

New Front Fuel RE541922 Back Fuel RE522878 Transmission AL221066
Inner air AL150288 Outer air AL172780 Hyd Filter AL169573

3218 9-17-21 Change oil JD 15w40 50R Filter RE504836
? ? ? 12-25-2021 New inside cab filters behind seat L214634

3506 2-10-2022 Change oil JD 15w40 50R Outer air AL172780 Hyd AL169573
3760 5-14-2022 New inner air AL150288 Front fuel RE541922 Back Fuel RE522878

3807 6-4-2022 Change oil 15w40 50R Filter RE504836 & put K17 in
Water separator filter RE533553
also Front Fuel

4138 12-13-2022 Change oil JD 15w40 Filter RE504836 also New inner air
RE 541922 Back Fuel RE 522878 Transmission AL221066
Hydraulic Filter AL169573

4499 4-5-2022 Change oil JD 15w40 50R Filter 504836 also New inner air
AL150288 & outer air AL172780

4637 6-7-2023 Change Front Fuel RE 541922 Back Fuel RE522878

hrs	hrs	4020	Parts
9-16-21	2012		overhaul injection pump
1-29-2022	2180	change oil	JD15w40 + 50 + 50 Der AR 2630
5-13-22	2342	change oil	AR 50041
10-24-2022	2492	change oil	JD15w40 + 50 + 50 Der AR 2630 + 50 Der AR 2630
2-7-23	2629	change oil	JD15w40 + 50 + 50 Der AR 2630 + 50 Der AR 2630
???	2740	change oil	JD15w40 + 50 + 50 Der AR 2630 + 50 Der AR 2630

change oil JD15w40 + 50 + 50 Der AR 2630 also
 change oil JD15w40 + 50 + 50 Der AR 2630 also
 Both back fives Titan 18,4 X34 \$1876.00 new tube
 in Back left fire almost new in Back Right (1 petal)